

Tvheadend - Bug #1747

Builds of 3.5.31052013 don't offer 8VSB option for muxes

2013-06-02 20:10 - Bob Lightfoot

Status:	Fixed	Start date:	2013-06-02
Priority:	Normal	Due date:	
Assignee:	John Törnblom	% Done:	0%
Category:	Muxers	Estimated time:	0.00 hour
Target version:		Affected Versions:	
Found in version:	3.5.31052013		
Description			
When trying to manually configure muxes only the options QAM-64 and QAM-256 are available, should have option 8VSB.			

History

#1 - 2013-06-02 20:12 - Bob Lightfoot

- File tvheadend-3.5.31052013-3.el6.lfoot.src.rpm added

#2 - 2020-05-15 15:13 - Fiore Systems

- Status changed from New to Fixed

Files

tvheadend-3.5.31052013-3.el6.lfoot.src.rpm	2.1 MB	2013-06-02	Bob Lightfoot
--	--------	------------	---------------