

## Tvheadend - Bug #3873

### Issues with BT Sport 1 HD and BT Sport 2 HD

2016-06-26 10:41 - AI B

<b>Status:</b> Invalid	<b>Start date:</b> 2016-06-26
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b>	<b>% Done:</b> 0%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b>	<b>Affected Versions:</b>
<b>Found in version:</b> 4.1-2130, 4.0.9	

**Description**

Im getting this error when trying to play BT Sport 1 HD:

2016-06-24 19:05:07.008 TS: Astra-28.2E-1/11385V/BT Sport 1 HD: H264 @ [#2332](#): Invalid start code 63:aa:4f

2016-06-24 19:05:07.029 TS: Astra-28.2E-1/11385V/BT Sport 1 HD: AC3 @ [#2333](#): Invalid start code 5a:84:d0

2016-06-24 19:05:07.080 TS: Astra-28.2E-1/11385V/BT Sport 1 HD: MPEG2AUDIO @ [#2334](#): Invalid start code 35:02:3b

and when trying BT Sport 2 HD:

2016-06-24 19:07:07.746 TS: Astra-28.2E-1/11385V/BT Sport 2 HD: H264 @ [#2337](#): Invalid start code 52:ec:b2

2016-06-24 19:07:07.754 TS: Astra-28.2E-1/11385V/BT Sport 2 HD: AC3 @ [#2338](#): Invalid start code 25:92:de

2016-06-24 19:07:07.809 TS: Astra-28.2E-1/11385V/BT Sport 2 HD: MPEG2AUDIO @ [#2339](#): Invalid start code ad:54:5e

According to OSCAM everything is fine the issue appears to be in tvheadend again. (Iv seen a few issues with similar before).

Similar Issues:  
<https://tvheadend.org/issues/2031#change-9334>  
<https://tvheadend.org/issues/3338>

I am using the latest git version 4.1-2130 and have also been told its happening on 4.0.9 aswell as a much earlier 4.1-XXXX version. All 3 version's are running on WeTek play's.

### History

#### #1 - 2016-07-03 22:23 - danny skjodt

Invalid start code 52:ec:b2

This usually happens when oscam gives a fake or wrong CW to tvheadend, send log from oscam.

#### #2 - 2016-07-04 00:01 - AI B

I just checked again so tvheadend shows:

2016-07-03 22:59:13.992 TS: Astra-28.2E-1/11385V/BT Sport 2 HD: H264 #2337: Invalid start code 06:3f:cf  
2016-07-03 22:59:15.715 TS: Astra-28.2E-1/11385V/BT Sport 2 HD: AC3 [#2338](#): Invalid start code 7e:4b:d2  
2016-07-03 22:59:15.780 TS: Astra-28.2E-1/11385V/BT Sport 2 HD: MPEG2AUDIO @ [#2339](#): Invalid start code dc:96:65

While trying to watch BT Sports HD 2

and OSCAM Log shows:

2016/07/03 22:55:21 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:FC33645A41F068AC4ABA5283FDA06D99): found (380 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:55:29 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:CEC4D4CE92E716A9D72EB23624E6C293): found (312 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:55:37 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:D76D8A2CA8BA30A7AC1D919B5007F384): found (307 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD

2016/07/03 22:55:45 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:924945D3F7E9272CBED0CDFCF93B1871): found (322 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:55:53 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:4C39787733E344874FD0A4B20CD55445): found (319 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:56:01 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:1265D852E56BE3C958D3333869F67FC8): found (348 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:56:09 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:E73B76106044657F8D0BB276515EDDAC): found (347 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:56:17 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:33C155E9D88415C1951CB684218C4573): found (241 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:56:25 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:AF5D670C0F4821FB05554AF0751B7482): found (418 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:56:33 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:9D5F9484FF62581072D1983F881B6AA6): found (256 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:56:41 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:155167C3E7D30E3FF9D24893FC61000B): found (304 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:56:49 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:A4209401BF17C37FCFADEE4F534073B4): found (310 ms) by CCCam-1 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:56:57 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:195EB3AA9D19E90C5BEA44F3EB7CF81B): found (230 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:57:05 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:DD50E16B309C39E095DE8DDEEF432496): found (324 ms) by CCCam-1 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:57:13 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:F5FDBC1537DC364BE80A5DE52D936F69): found (336 ms) by CCCam-1 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:57:21 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:107293A5D6AE1551C8EE7573B9F3224E): found (459 ms) by CCCam-3 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:57:29 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:950C4892BB50F3B447447412CE353DE0): found (359 ms) by CCCam-1 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:57:37 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:BD9C8AB558D13F2D26A97E7C44FCC5D7): found (202 ms) by CCCam-1 (P/2/4/4) - BT Sport 2 HD  
2016/07/03 22:57:45 661CC661 c (ecm) tvh (0963@000000/FFFF/C5E9/6C:DACBFDD290DA4B5EF5808D6ED133E475): found (441 ms) by CCCam-1 (P/2/4/4) - BT Sport 2 HD

### #3 - 2016-07-04 18:56 - gary tan

The BT channels have the gone same way as all the other HD channels i.e. you can only watch them now with an official receiver.

### #4 - 2016-07-04 20:30 - Mark Clarkstone

- Status changed from New to Invalid

Setting as invalid as this isn't a Tvheadend issue.