

Tvheadend - Bug #1244

webui - dvb adapter selection dropdown

2012-09-23 02:51 - Dave Chapman

Status:	Fixed	Start date:	2012-09-23
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:	User Interface	Estimated time:	0.00 hour
Target version:		Affected Versions:	
Found in version:	3.1.718.g81be9		
Description			
<p>My DVB server contains 3 DVB cards - a quad DVB-T2, a dual DVB-T and a single DVB-S. These are listed as follows in the DVB adapter configuration drop-down list:</p> <p>TurboSight TBS 62x0 DVBT/T2 frontend TurboSight TBS 62x0 DVBT/T2 frontend TurboSight TBS 62x0 DVBT/T2 frontend TurboSight TBS 62x0 DVBT/T2 frontend DiBcom 7000PC DiBcom 7000PC ST STV0299 DVB-S</p> <p>If I select, for example, the second DiBcom tuner, then when I go back to the drop-down list to select another adapter, then the first DiBcom tuner is highlighted. Similarly, if I select any of the TBS tuners, the first one is always selected when I go back to the list.</p> <p>So it looks like the default is being chosen based on name, rather than adapter number.</p>			

History

#1 - 2012-09-23 10:39 - Dave Chapman

- Category set to 11

#2 - 2012-10-24 11:59 - Adam Sutton

- Status changed from New to Accepted

- Target version set to 3.4

This is a fairly trivial, albeit annoying, issue. I don't think this will be backported to 3.2 when its fixed.

It can easily be worked around by simply renaming each adapter to have a unique name.

Adam

#3 - 2013-01-20 01:26 - Adam Sutton

- Target version deleted (3.4)

#4 - 2014-04-17 00:02 - Mark Clarkstone

- Status changed from Accepted to Resolved

#5 - 2014-04-22 00:01 - Adam Sutton

- Status changed from Resolved to Fixed